



NOTES:  
20. COMPRESS GASKET UNTIL ALL METAL STOPS (12 PLACES) STRIKE MOUNTING SURFACE. USE SCREW AND SEALS PROVIDED.