



**NOTES:**

1. MOUNT R41 (SPEED POT) IN THE RIGHT MOST AVAILABLE POSITION IN END OF S3 SWITCHES.
2. APPLY LABEL 124949 AS SHOWN WHEN THERE ARE NO P3/P21 OR P4/P41 OPTIONS. IF EITHER P3/P41 OR P3/P21 OPTION IS ORDERED, APPLY THE HOT SURFACE LABEL "HOT" CENTERED ABOVE THE 124949 LABEL.
3. FOLLOW ALL MPWS PROCEDURES, VENDOR SUPPLIED LITERATURE, AND SUPPLIED DOCUMENTATION FOR COMPONENT PLACEMENT AND ASSEMBLY.
4. WHEN OPTION P41 IS ORDERED, MOUNT L112L3 LABELS ON THE BOTTOM AND T1, T2, T3 LABELS ON THE TOP WIRE FROM TOP TO THE DRIVE.
5. WHEN OPTION P41 IS ORDERED, MOUNT L112L3 ON THE TOP AND T1, T2, T3 ON THE BOTTOM WIRE FROM BOTTOM TO THE DRIVE.
6. WHEN OPTION P3 IS ORDERED, APPLY LABEL 344314 AND TERMINAL ADAPTER 344364 TO THE TOP AND BOTTOM OF MCP1 RESPECTIVELY. WIRE FROM THE TOP (T1, T2, T3) TO THE DRIVE.
7. WHEN OPTION P21 IS ORDERED, DO NOT USE THE ABOVE PARTS. WIRE FROM BOTTOM OF MCP1 (T1, T2, T3) TO THE DRIVE.
8. "INDOOR USE ONLY" LABEL, USE WITH NEMA 4 OR NEMA 4X WITH DOOR MOUNTED HIM ENCLOSURES ONLY.

NOTE 4

<table border="1"> <tr><td>14-21</td><td>122947</td></tr> <tr><td>18-21</td><td>122948</td></tr> <tr><td>19-21</td><td>122949</td></tr> <tr><td>19-15</td><td>122954</td></tr> <tr><td>19-15</td><td>122955</td></tr> </table>	14-21	122947	18-21	122948	19-21	122949	19-15	122954	19-15	122955	<table border="1"> <tr><td>ACAD</td><td>12-15-04</td></tr> <tr><td>ACS</td><td>12-15-04</td></tr> <tr><td>ACS</td><td>12-15-04</td></tr> <tr><td>MPWS P41/21</td><td></td></tr> <tr><td>MPWS P41/21</td><td></td></tr> <tr><td>MPWS P41/21</td><td></td></tr> </table>	ACAD	12-15-04	ACS	12-15-04	ACS	12-15-04	MPWS P41/21		MPWS P41/21		MPWS P41/21		<p><b>Rockwell Automation</b> <b>Allen-Bradley</b></p> <p>LAYOUT DRAWING OF 3PH AC DRIVE NEMA 4X/12-(7.5-15 HP) 3PH, 480V</p> <p>C-349932-3</p>
14-21	122947																							
18-21	122948																							
19-21	122949																							
19-15	122954																							
19-15	122955																							
ACAD	12-15-04																							
ACS	12-15-04																							
ACS	12-15-04																							
MPWS P41/21																								
MPWS P41/21																								
MPWS P41/21																								