

V8200, VR8200, VR8201 Continuous Pilot Combination Gas Controls

ADDENDUM

Form 69-0234-5 is amended as follows:

Add the following caution on page 1 after Table 3:



CAUTION

Equipment Damage Hazard
Improper installation can cause equipment damage.

The V8200F is not functionally equivalent to other V8200 models and they should not be used interchangeably. The V8200F is a non-redundant valve and is not suitable for applications that require dual shutoff valves. If the application requires a redundant shutoff function, a VR8200 Valve should be used. The V8200F includes a step-opening feature. Use of a valve with non-step opening characteristics could produce a rough light-off, resulting in nuisance shutdowns or possible damage to the appliance.

Home and Building Control

Honeywell Inc.
Honeywell Plaza
P.O. Box 524
Minneapolis, MN 55408-0524

Home and Building Control

Honeywell Limited-Honeywell Limitée
155 Gordon Baker Road
North York, Ontario
M2H 3N7

