



**PRODUCT DISCONTINUATION NOTICE**

**PDN No.: USA 2013/010**

<b>IXYS PRODUCT TYPE:</b> IXFN44N50U2, IXFN48N50U2 IXFN44N50U3, IXFN48N50U3	<b>TYPE:</b> HIPERFET POWER MOSFET	<b>RECOMMEND REPLACEMENT:</b> SEE BELOW
-----------------------------------------------------------------------------------	---------------------------------------	--------------------------------------------

USE THE REPLACEMENT: **IXFN64N50PD2** FOR IXFN44N50U2 & IXFN48N50U2

USE THE REPLACEMENT: **IXFN64N50PD3** FOR IXFN44N50U3 & IXFN48N50U3

REASON FOR DISCONTINUATION: OBSOLETE TECHNOLOGY

LAST TIME ORDER DATE: PLEASE CONTACT IXYS CORPORATION, MILPITAS, CA USA

LAST TIME DELIVERY DATE: PLEASE CONTACT IXYS CORPORATION, MILPITAS, CA USA

INTERNAL REFERENCE:

In case of any question, please contact: Sudhir Kommineni [s.kommineni@ixys.net](mailto:s.kommineni@ixys.net)

INITIATOR GORDON ROSETE	TITLE/FUNCTION DEPT. HEAD QA	DATE AUGUST 28, 2013	E-MAIL G.ROSETE@IXYS.NET
----------------------------	---------------------------------	-------------------------	-----------------------------

**CUSTOMER RESPONSE:**

(PLEASE FILL IN AND RETURN BY E-MAIL, FAX OR MAIL WITHIN 4 WEEKS)

<input type="checkbox"/> for further questions/ information please comment	Company: _____ Name & Position _____ Phone / Fax No: _____
-------------------------------------------------------------------------------	------------------------------------------------------------------

COMMENTS: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_